



**LOS ANGELES/LONG BEACH
HARBOR SAFETY COMMITTEE**

Mandated by
California Oil Spill Prevention and
Response Act of 1990

June 30, 2009

Harbor Safety Plan Revision Instructions

If you wish to update a copy of the 2008 LA/LB HSP to show the revisions for 2009 please follow the instruction below on what to replace, add or delete:

<u>Revised Sections in 2009</u>	<u>Replace all pages in these sections unless noted</u>
Table of Contents	Replace
Table of Appendix	Replace
Introduction & Committee Members	Replace
Executive Summary: Recommendations	Replace
Vessel Operating Procedures (VOP)	Replace
Chapter VI Contingency Routing	Replace
Chapter VII History of Accidents and "Near Misses"	Replace
Chapter XIV Underkeel Clearance	Replace
Chapter XVII Inclement Weather: Standards of Care for Vessel Movements (formerly called Inclement Weather)	Replace
Chapter XVIII Reduced Visibility: Standards of Care --- (this chapter has been absorbed into Chapter XVII)	DELETE
Appendix B Users Manual, U.S. Coast Guard/Marine Exchange VTS	Replace
Appendix C Tug Escort/Assist Information Page	Replace
Appendix C.1 Listing of Tugboats - Bollard Certified and letters from Calif. DF&G/OSPR	Replace

c/o Marine Exchange of Southern California
P. O. Box 1949 • San Pedro • California 90733-1949
Telephone 310 519-3134 • Fax 310 241-0300
E-mail: HSC@mxsocal.org

Note: For your ready reference, the revised LA/LB Harbor Safety Plan for 2009 will be posted to the Marine Exchange web site (www.mxsocal.org), including a “printer friendly” version. Copies of the LA/LB HSP are also available on CD and in hard copy by request to the Marine Exchange.